NSWalks HALIFAX

Walking Audit Project Cherry Brook

Presentation to Active Transportation Advisory Committee February 13, 2025















Welcome & Introductions

Objectives of meeting:

- 1. Share & discuss results of walking audit
- 2. Recommend that HRM staff participate in future walking audits
- 3. Recommend the construction of a sidewalk on Cherry Brook Road (from Graham Creighton Junior High to Church)
- 4. Discuss possible next steps

History of Project

Hike NS Pilot project funded by Connect2 (Province of Nova Scotia)

Goal: To improve walkability in communities through engagement and awareness of challenges

Cherry Brook - one of 10 communities across the province in the Pilot

Cherry Brook Walking Audit event took place on Saturday, November 2nd, 2024

Walking Audit Organizers

Carmalee Netu - Community Champion and CMT member- Cherry Brook

Anders Turim - Active Transportation Planner - HRM

Catherine Droesbeck - Hike Nova Scotia



Cherry Brook Walking Audit Participants

- 2 community members (plus CMT)
- HRM Planner
- HRM Engineer
- HRM Manager of Urban Forestry
- Province of NS employee (manager)
- Member of Community Mobilization Team
- Community Health Board member
- Ecology Action Centre Planner
- Hike Nova Scotia staff member
- (Municipal Councillor unable to attend)

Total: 10 people



Why a Walking Audit in Cherry Brook?

Frequent requests for sidewalk


HRM staff is aware of the need due to:

- Disconnected bus stops
- Cherry Brook being a Minor Collector Road
- Proximity to a Junior High, places of worship, community centre and playground
- Relatively high levels of socioeconomic need

Walking audit presented opportunity to engage with community and have staff gain an understanding of the walking experience and community in Cherry Brook







Walking Audit Tool

NSWalks WALKABILITY AUDIT TOOL

COMMUNITY: Thank you for participating in our commun		c, review
the audit to familiarize yourself with the co items in each section. At the end of the aud responses will be combined to create an ov community.	dit, add the totals from each se	ction. Your
SIDEWALKS Rating: 0 - 5		
There are sidewalks		/5
The sidewalk is continual (not starting a	and stopping)	/5
The sidewalk is easy to walk/roll on		/5
➤ The sidewalk is safe (ex: salting, snow p	plowed, filled cracks)	/5
► The sidewalk is wide enough		/5
	Tot	al:/25
APPEAL Rating: 0 - 5	SAFETY Rating: 0 - 5	
The area is clear of litter/5	➤ There is enough lighting	/5
The route is nice/pleasant/5	➤ There are other people walking the route	/5
There are trees/plants/5	You can see other peopl coming/they can they se	
		otal:/15

NSWalks WALKABILITY AUDIT CROSSING Ratina: 0 - 5 TRAFFIC Rating: 0 - 5 The speed limit is posted ___/5 ► There are crosswalks ► The drivers follow the speed There are enough crosswalks ___/5 ➤ The crosswalk location ► There are things that calm ___/5 makes sense traffic (ex: speed bumps, curb bump outs) ➤ There is enough time to cross the road There is protection for people walking from cars on the road The crosswalks are safe (ex: flashing lights, flags, ► There is too much traffic and crossing guards) Total: ___/25 Total:___/25 FACILITIES Rating: 0 - 5 HOW WALKABLE IS YOUR COMMUNITY? There is street furniture: Add up the totals from each section. benches /120 garbage cans bike racks Below 60 It's a disaster for walking! There is enough signage: Maps 60-79 Okay, but it needs work. Street signs 80-99 Pretty good - not very many issues. There are trees for 100-120 Let's celebrate! shade/shaded areas Total:___/15 We have a great community for walking. Notes:

Walking Audit Results

Sidewalks: 0/25

Appeal: 9/15


Safety: 4/15

Crossing: 6/25

Traffic: 11/25

Facilities: 6/15

Overall rating: 30/120 - "A disaster for walking"



Community Food cupboard

Key Findings

No sidewalks, paved shoulders, or separate space for walking

Steep ditch at several points

Curve in road creates significant safety hazards

Quotes from Walking Audit participants:

- "The segments where there are curves are incredibly dangerous"
- "Extremely unsafe to walk..."



Key Findings - Facilities

Inadequate space for bus stop

Trimming of plants could make more room for people walking

Walking Audit participants:

 "...No lights for bus stops. Bus Stop signs are hidden by trees. No garbage cans or benches with bus stops. Not safe to walk at night because of no lights."



Recommendations & Next Steps

The results of this audit indicate that there is a <u>high</u> need for sidewalk on Cherry Brook Road from Graham Creighton Junior High to Cherry Brook United Baptist Church.

HRM staff recommend moving this project into the detailed design phase and adding it to the 5-Year Capital Plan where implementation will be based on project feasibility, priority and budget availability.

Walking audits can be a useful way for municipal staff to meet with community members and get on the ground understanding of the walking experience. This is something that could be done more as an organization.

Questions & Comments

We invite any questions or comments you may have!



Thank you and feel free to contact us

Catherine Droesbeck, Hike Nova Scotia walk@hikenovascotia.ca

Anders Turim, Active Transportation Planner, HRM anders.turim@halifax.ca













